Printed on: 2/17/2013 11:43:24 AM

National Transportation Safety Board	NTSB	ID: DCA08MA0	98	Aircraft Registration Number: N999LJ						
FACTUAL REPORT	Occurr	ence Date: 09/1	9/2008	Most Critical Injury: Fatal						
AVIATION	Occurr	ence Type: Acci	dent	Investigated B	y: NTS	В				
Location/Time										
Nearest City/Place	State	Zip Code	Local Time	Time Zone						
Columbia	sc		2353	EDT						
Airport Proximity: Off Airport/Airstrip	Airport Proximity: Off Airport/Airstrip Distance From L				Landing Facility: 0.5					
Aircraft Information Summary										
Aircraft Manufacturer	Model/Serie	es	Type of Aircraft							
Learjet	LR60			Airplane						
Revenue Sightseeing Flight: No		Air	Medical Transport							

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

*** Note: NTSB investigators traveled in support of this investigation and used data obtained from various sources to prepare this aircraft accident report. ***

The NTSB's full report is available at http://www.ntsb.gov/publictn/publictn.htm. The Aircraft Accident Report number is NTSB/AAR-10/02.

On September 19, 2008, about 2353 eastern daylight time, a Bombardier Learjet Model 60, N999LJ, owned by Inter Travel and Services, Inc., and operated by Global Exec Aviation, overran runway 11 during a rejected takeoff at Columbia Metropolitan Airport, Columbia, South Carolina. The captain, the first officer, and two passengers were killed; two other passengers were seriously injured. The nonscheduled domestic passenger flight to Van Nuys, California, was operated under 14 Code of Federal Regulations Part 135. Visual meteorological conditions prevailed, and an instrument flight rules flight plan was filed.

Updated on Jul 16 2010 4:51PM

National Transportation Safety Board FACTUAL REPORT

NTSB ID: DCA08MA098

Occurrence Date: 09/19/2008

AVIATION		Occurrence Type: Accident										
Landing Facility/Approach In	formation	•										
Airport Name		Air	port ID:	Airp	oort Elevation	Rur	nway Used	way Used Runway Leng			Runv	vay Width
Columbia Metropolitan	Columbia Metropolitan KC					Ft. MSL 11					150	
Runway Surface Type: Asphalt												
Runway Surface Condition: Dry												
Approach/Arrival Flown: NONE	Ē											
VFR Approach/Landing: None												
Aircraft Information												
Aircraft Manufacturer Learjet			Model/ LR60		es				Serial	Numbe	er	
Airworthiness Certificate(s): Trans	sport		•						•			
Landing Gear Type: Tricycle												
Amateur Built Acft? No	Number of Seats:	10	Certified	d Max	x Gross Wt.		23500	Numbe	per of Engines: 2			
Engine Type:							Model/Se	ries:			Rate	d Power:
- Aircraft Inspection Information												
Type of Last Inspection		Da	ate of Last	t Insp	ection	Time S	ince Last Insp	ection		Airframe Total Time		
								Ho	ours			108 Hours
- Emergency Locator Transmitter (ELT) Information					•						
ELT Installed?/Type Yes / Unkno)wn	El	ELT Operated? No ELT Aided in Locating Accident Site?						? No			
Owner/Operator Information		<u>'</u>				•						
Registered Aircraft Owner			Street A	Addre	ss							
Inter Travel and Services			City								te	Zip Code
			Street A	ddres	SS							
Operator of Aircraft		,								Stat	. 1	71.0.1
Global Exec Avaition				City Long Beach C/								Zip Code
Operator Does Business As:				С	perator Desig	nator Co	ode:					
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s)	: On-demand Air 1	Гахі										
Operating Certificate:					Operator Certi	icate:						
Regulation Flight Conducted Unde	r: Part 135: Air Ta	xi & Com	muter	•								
Type of Flight Operation Conducted	d: Non-scheduled	; Domesti	c; Passe	enger	Only							
	J	FACTUA	L REPO	RT -	AVIATION							Page 2

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DCA08MA098

Occurrence Date: 09/19/2008

		NI VICI					,, .									
AVIATION Occurrence Type:						ce Type: Ac	cide	ent								
First Pilo	t Information															
Name		City	ity Stat					ate	Dat	e of Birth	Age					
On File																
Sex: F					Ce	rtifica	ite Num	ber:		-						
Certificate((s): Airlin	ne Transpo	ort													
Airplane R	ating(s):															
Rotorcraft/	Glider/LTA:															
Instrument	Rating(s):															
Instructor F	Rating(s):															
Current Bie	ennial Flight Revie	ew?														
Medical Ce	ert.:	Medi	cal Cert. S	Status	3:						Date of La	ast M	ledical E	Exam	n:	
		•														
- Flight Tin	ne Matrix	All A/C	This Make		Airplane Single Engine	Airplane Mult-Engine	Night Instr		Instrum	ent Simulated	Ro			Glider	Lighter Than Air	
Total Time																
Pilot In Co	mmand(PIC)													\Box		
Instructor							_									
Instruction	Received															
Last 90 Da	ays															
Last 30 Da	ays															
Last 24 Ho	ours	<u> </u>														
Seatbelt Us	sed? Yes	Sh	oulder Hai	ness	Used? Yes			Toxico	Toxicology Performed? Second						nd Pilot? Ye	S
Flight Pla	an/Itinerary															
Type of Flig	ght Plan Filed: IF	R														
Departure	Point							State	State Airport Id			Identifier Depart			e Time	Time Zone
Same as	Same as Accident/Incident Location								KCA				2353			EDT
Destination	า							State	State Airn			rport Identifier				
Van Nuys								CA								
Type of Clo	earance: IFR							•	•							
Type of Air	rspace:															
Weather	Information															
Source of	Wx Information:															
	Autom	nated Repo	ort													
					FACTUAL	REPORT	- A\	VIATION	٧							Page 3
							4 1		•							U

National Transportation Safety Board

FACTUAL REPORT

NTSB ID: DCA08MA098

Occurrence Date: 09/19/2008

7 % V 2 2			Occurrence Type: Accident												
AVIATION									Occ						
Weather	Information		<u> </u>	<u> </u>					_						
WOF ID	Observation Time	Time Zone	WOF	Elevation	\Box	WOF Distance From Accident Site					Direction From Accident Site				
CAE	2345	EDT		Ft. MS	iL		NM				Deg. Mag				ig.
Sky/Lowes	st Cloud Condition: Clear	r					Ft. AGL Condition of Light: Night								
Lowest Ce	eiling: None			Ft. AGI		Visibi	ility:	10	SM	Alti	meter:	;	30.23		"Hg
Temperati	ure: -7 °C I	Dew Point:	-10	0 °C W	/eath	er Condi	tions at Ac	cident S	Site: Visual	Conc	litions				
Wind Dire	ction: 60	Wind Spe	eed: 7			Wind	d Gusts: 1	4							
Visibility (F	RVR): Ft.	Visibility	(RVV)	SI	М										
Precip and	d/or Obscuration:														
Accident	t Information														
			Aircr	aft Fire: G	roun	nd			Aircraft Exp	olosio	n				
	t Information amage: Destroyed		Aircr	raft Fire: G	roun	d			Aircraft Exp	olosio	n				
Aircraft Da		Fatal	Aircr	raft Fire: G		d	TOTAL		Aircraft Exp	olosio	n				
Aircraft Da	ummary Matrix	Fatal 1						1	Aircraft Exp	olosio	n				<u> </u>
Aircraft Da	amage: Destroyed ummary Matrix							1 1	Aircraft Exp	olosio	n				
- Injury Su First P	amage: Destroyed ummary Matrix	1						1 1	Aircraft Exp	olosio	n				
- Injury Su First P Secon Studer	ummary Matrix vilot	1						1 1	Aircraft Exp	olosio	n				
- Injury Su First P Secon Studer	amage: Destroyed ammary Matrix bilot d Pilot nt Pilot Instructor	1						111	Aircraft Exp	olosio	n				
- Injury Su First P Secon Studer Flight	amage: Destroyed ammary Matrix bilot d Pilot nt Pilot Instructor	1						1 1 1	Aircraft Exp	olosio	n				
- Injury Su First P Secon Studer Flight I Check	amage: Destroyed Immary Matrix Pilot Ind Pilot Instructor Pilot	1						1 1 1	Aircraft Exp	olosio	n				
- Injury Su First P Secon Studer Flight I Check	amage: Destroyed Immary Matrix Pilot Int Pilot Instructor Pilot Engineer Attendants	1						1 1 1	Aircraft Exp	olosio	n				
- Injury Su First P Secon Studer Flight I Check Flight I Cabin	amage: Destroyed Immary Matrix Filot Ind Pilot Instructor Pilot Engineer Attendants Crew	1						1 1 1 4	Aircraft Exp	olosio	n				
- Injury Su First P Secon Studer Flight I Check Flight I Cabin Other I	amage: Destroyed Immary Matrix Filot Ind Pilot Instructor Pilot Engineer Attendants Crew	1	Serious					1	Aircraft Exp	olosio	n				
- Injury Su First P Secon Studer Flight I Check Flight I Cabin Other I Passer	amage: Destroyed ammary Matrix vilot d Pilot Instructor Pilot Engineer Attendants Crew Ingers	1	Serious 2					1 4	Aircraft Exp	olosio	n				

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: DCA08MA098

Occurrence Date: 09/19/2008

Occurrence Type: Accident

Administrative	1 - 4 4

Investigator-In-Charge (IIC)

William R. English

Additional Persons Participating in This Accident/Incident Investigation:

Vikki Anderson AAI-100